

 Date:
 2024.02.22

 Dock Firmware:
 V01.06.1704*

 Aircraft Firmware:
 V09.01.0006*

 Intelligent Flight Battery:
 V02.00.20.58

 Remote Controller Firmware:
 V03.02.0907*

 DJI Pilot 2 App:
 V9.1.0.21

DJI Pilot 2 App: V9.1.0.21

DJI Assistant 2 (Enterprise Series): V2.1.12

Firmware Update Method DJI Dock: DJI FlightHub 2 / DJI Assistant 2

Aircraft: DJI FlightHub 2 / DJI Assistant 2 / App

Remote Controller: DJI Assistant 2 / App

The built-in DJI Pilot 2 App: will be updated with the Remote

Controller firmware

What's new

DJI Dock

- Added support for Trial Flight. Users can assess the task performance and media file transfer performance after completing dock configuration.
- Added support for Silent Mode. In Silent Mode, the operation noise will be reduced and the cooling performance of the air conditioning system will be affected.
- Added support for enabling obstacle data settings to improve flight safety. Go to the <u>DJI FlightHub 2 User</u> <u>Guide</u> and refer to the Map Task Area section for more information.
- Added support for transferring and managing the unlocking licenses and updating flight safety database in DJI FlightHub 2.
- Optimized functions in DJI FlightHub 2. Refer to the DJI FlightHub 2 Release Note for more information.

Notes:

- Visit https://www.dji.com/dock/downloads to download manuals such as the Quick Installation Guide, Safety Guidelines, and User Manual.
- Visit https://www.dji.com/dock/video to watch the tutorial videos.
- Visit https://www.dji.com/flighthub-2 for more information on DJI FlightHub 2.
- Scan the QR code to contact DJI Support:



^{*} Make sure to update the firmware version for the aircraft, the remote controller, and the dock. Otherwise, they will not be compatible with each other.



Date: 2023.12.28

Dock Firmware: V01.05.0908*

Aircraft Firmware: V09.00.0503*

Intelligent Flight Battery: V02.00.20.58

Remote Controller Firmware: V02.02.0803*

DJI Pilot 2 App: V9.0.5.39

DJI Assistant 2 (Enterprise Series): V2.1.12

Firmware Update Method DJI Dock: DJI FlightHub 2 / DJI Assistant 2

Aircraft: DJI FlightHub 2 / DJI Assistant 2 / App

Remote Controller: DJI Assistant 2 / App

The built-in DJI Pilot 2 App: will be updated with the Remote

Controller firmware

What's new

Matrice 30 Series Dock Version aircraft

- Fixed some minor bugs.
- Added some functions to meet local regulation requirements.

Notes:

- Visit https://www.dji.com/dock/downloads to download manuals such as the Quick Installation Guide, Safety Guidelines, and User Manual.
- Visit https://www.dji.com/dock/video to watch the tutorial videos.
- Visit https://www.dji.com/flighthub-2 for more information on DJI FlightHub 2.
- Scan the QR code to contact DJI Support:



^{*} Make sure to update the firmware version for the aircraft, the remote controller, and the dock. Otherwise, they will not be compatible with each other.



Date: 2023.11.23

Dock Firmware: V01.05.0905*

Aircraft Firmware: V08.00.0003*

Intelligent Flight Battery: V02.00.20.58

Remote Controller Firmware: V02.02.0405*

DJI Pilot 2 App: V7.1.0.32

DJI Assistant 2 (Enterprise Series): V2.1.11

DJI Dock: DJI FlightHub 2 / DJI Assistant 2

Aircraft: DJI FlightHub 2 / DJI Assistant 2 / App

Firmware Update Method Remote Controller: DJI Assistant 2 / App

The built-in DJI Pilot 2 App: will be updated with the Remote

Controller firmware

What's new

DJI Dock

• Fixed an occasional error prompt related to the air conditioning system's heater.

Notes:

- Visit https://www.dji.com/dock/downloads to download manuals such as the Quick Installation Guide, Safety Guidelines, and User Manual.
- Visit https://www.dji.com/dock/video to watch the tutorial videos.
- Visit https://www.dji.com/flighthub-2 for more information on DJI FlightHub 2.
- Scan the QR code to contact DJI Support:



^{*} Make sure to update the firmware version for the aircraft, the remote controller, and the dock. Otherwise, they will not be compatible with each other.



Date: 2023.10.12

Dock Firmware: V01.05.0902*

Aircraft Firmware: V08.00.0003*

Intelligent Flight Battery: V02.00.20.58

Remote Controller Firmware: V02.02.0405*

DJI Pilot 2 App: V7.1.0.32

DJI Assistant 2 (Enterprise Series): V2.1.11

Firmware Update Method DJI Dock: DJI FlightHub 2 / DJI Assistant 2

Aircraft: DJI FlightHub 2 / DJI Assistant 2 / App

Remote Controller: DJI Assistant 2 / App

The built-in DJI Pilot 2 App: will be updated with the Remote

Controller firmware

What's new

Matrice 30 Series Dock Version aircraft

• Improved aircraft flight stability.

Notes:

- Visit https://www.dji.com/dock/downloads to download manuals such as the Quick Installation Guide, Safety Guidelines, and User Manual.
- Visit https://www.dji.com/dock/video to watch the tutorial videos.
- Visit https://www.dji.com/flighthub-2 for more information on DJI FlightHub 2.
- Scan the QR code to contact DJI Support:



^{*} Make sure to update the firmware version for the aircraft, the remote controller, and the dock. Otherwise, they will not be compatible with each other.



Date: 2023.09.18

Dock Firmware: V01.05.0902*

Aircraft Firmware: V07.01.0026*

Intelligent Flight Battery: V02.00.20.58

Remote Controller Firmware: V02.02.0405*

DJI Pilot 2 App: V7.1.0.32

DJI Assistant 2 (Enterprise Series): V2.1.11

Firmware Update Method DJI Dock: DJI FlightHub 2 / DJI Assistant 2

Aircraft: DJI FlightHub 2 / DJI Assistant 2 / App

Remote Controller: DJI Assistant 2 / App

The built-in DJI Pilot 2 App: will be updated with the Remote

Controller firmware

What's new

DJI Dock

- Updated the RTH to Advanced RTH.
- Optimized battery safety strategy. The dock cannot perform Continuous or Timed tasks if the battery cycle count exceeds 500 cycles. Immediate tasks and FlyTo tasks will not be affected.
- Added support to stop the flight route task after pressing the emergency stop button when the dock is preparing for the flight route task.
- Optimized the operation logic of the air conditioning system to reduce the fan noise when the air conditioning system is idle.

DJI FlightHub 2

- Added support for the aircraft to bypass GEO Zones when performing FlyTo tasks or during RTH.
- Added support to improve safety of RTH and safe Resume Task from Breakpoint. When editing the waypoints, the waypoint can be marked as a no-return point, and the flight route to its previous and next waypoints will be marked as a no-return area. The aircraft will fly along the flight route to exit the no-return area before performing RTH or Resume Flight from Breakpoint.
- Added support for DJI AirSense to improve flight safety.
- Added support to manage custom flight areas and GEO Zones in Flight Area Management, allowing for more flexible flight plans.
- Added support to control PSDK payloads in DJI FlightHub 2.
- Added support to set the palette, enable side-by-side view in the IR camera view, using RNG, and Face PinPoint in the livestream view after obtaining payload control.
- Optimized the warning messages for emergencies such as alternate landing, incorrect landing locations, or unable to land on the dock.

^{*} Make sure to update the firmware version for the aircraft, the remote controller, and the dock. Otherwise, they will not be compatible with each other.



DJI Pilot 2

- Added warnings when configuring the dock in GEO zones.
- Added support for site selection using the DJI Mavic 3 Enterprise Series aircraft when configuring the dock.
- Added support to check the network connection for the dock.

Notes:

- Visit https://www.dji.com/dock/downloads to download manuals such as the Quick Installation Guide, Safety Guidelines, and User Manual.
- Visit https://www.dji.com/dock/video to watch the tutorial videos.
- Visit https://www.dji.com/flighthub-2 for more information on DJI FlightHub 2.
- Scan the QR code to contact DJI Support:





Date:	2023.07.18
Dock Firmware:	v01.04.0705*
Aircraft Firmware:	v07.00.0146*
Intelligent Flight Battery:	v02.00.20.58
Remote Controller Firmware:	v01.02.0445*
DJI Pilot 2 App:	v7.0.3.9

DJI Assistant 2 (Enterprise Series): v2.1.10

Firmware Update Method DJI Dock: DJI FlightHub 2 / DJI Assistant 2

Aircraft: DJI FlightHub 2 / DJI Assistant 2 / App

Remote Controller: DJI Assistant 2 / App

The built-in DJI Pilot 2 App: will be updated with the Remote

Controller firmware

What's new

DJI Dock

- Added support to reset standard maintenance count for the dock in DJI Pilot 2.
- Optimized the RTH logic in strong wind conditions. The aircraft will return to home if the wind speed is too high.

Notes:

- Visit https://www.dji.com/dock/downloads to download manuals such as the Quick Installation Guide, Safety Guidelines, and User Manual.
- Visit https://www.dji.com/dock/video to watch the tutorial videos.
- Visit https://www.dji.com/flighthub-2 for more information on DJI FlightHub 2.
- Scan the QR code to contact DJI Support:



^{*} Make sure to update the firmware version for the aircraft, the remote controller, and the dock. Otherwise, they will not be compatible with each other.